



info@bridgemate.nz

Thu, Nov 2, 9:22 PM (12
hours ago)

to info, bcc: me

Hi All

Over the last year or so I have been approached by a few clubs, who have Bridgemate units with pixels missing.

All these clubs were given the same advice, as in that if the club is considering upgrading their current electronic scoring set up, that perhaps they should wait with replacing the displays because Bridgemate 3 is close to being launched. This was mentioned to me two years ago I have to say by Bridgemate head office. They are currently in the testing phase of BM3.

The display replacements were rather pricey per unit as they had to be sent to NL. Depending on how many units were sent at the same time, postage (Fedex) would have been divided over the number of units sent, it still ended up around \$90 per unit.

I can now offer this service to be done in NZ for \$60 incl GST, excluding NZ postage, per unit. Displays still have to come from NL and be paid in Euro's, which still doesn't make it cheap, but at least it is a lot better than it was, now not having to send the units to NL.

If you would like to use this service, please advise me by 17 November, so I can do a bulk order.

If you have faded keypads, these can be replaced for \$28.00 incl GST, excluding postage.

Kind regards

Jan Spaans

Bridgemate NZ

021 150 1725.